
#### Flare Fitting Tightening Torque Mitsubishi








#### Flare Fitting Tightening Torque **Fujitsu**






manufacturer for R-32 heat pumps and should only be used as a reference. Always check the manufacturer provided

# Flare Fitting Tightening Torque Daikin








# Flare Fitting Tightening Torque Haier








#### Flare Fitting Tightening Torque Lennox






#### Flare Fitting Tightening Torque

LG








### Flare Fitting Tightening Torque Carrier








# Flare Fitting Tightening Torque Samsung






### **SAMSUNG**

# Flare Fitting Tightening Torque Durastar








#### Flare Fitting Tightening Torque










## Flare Fitting Tightening Torque Midea








#### Flare Fitting Tightening Torque







# Flare Fitting Tightening Torque Kinghome



